Impact 12.2.6 - Release Notes

Welcome to Impact, a complete range of software and hardware to solve your machine vision needs. Impact is the most complete product line with the same software used throughout. Impact reduces your cost of ownership and provides you with the flexibility that today's quickly changing manufacturing environment requires.

These Release Notes describe enhancements in this software release, along with known bugs that were fixed.

Check our website at www.datasensing.com/ for any newer releases, information on other Impact software and hardware products, and technical support.

This document is divided into the following sections:

Major Bugs Fixed in this release

Readme Documentation

Major Bugs fixed in this release

- [Fixed] ModBus crashing when trying to read/write an address higher than 127
- [Fixed] Crash in Circle Gauge tool with stitched images
- [Fixed] String Build - Input "Date And Time" show incorrect date.
- [Fixed] Display button into tool panel is hidden when decreasing the window size.
- [Fixed] SVS camera failure
- [Fixed] Warning Message when you Run a task from SDK Methods
- [Fixed] SDK Vision Image bitmap Conversion
- [Fixed] MX-E90 Profinet Connection problem at the startup

Readme Documentation

More information can be found in *readme.pdf* file in documentation folder inside VPM installation.